

XFI	Pink Conn	Lt. Gray Conn	Wire Color On Adapter	WBO2	Notes	Wire Color On NTK Sensor
C1	C16	B	White	UEGO P+		White
C2	D16	A	Black	UEGO P-		Black
C3	D14	C	Red	UEGO S+		Gray
C4	D13	E	Gray	UEGO R+		(Calibration Resistor)
C5	C14	F	Blue	UEGO R-		(Calibration Resistor)
C6	C15	G	Yellow	UEGO H-		Yellow
		H	Orange	Vss	Switched 12V	Blue

Wide Band O2 Sensor Chart

This chart shows pinouts that feed through the 108112 Adapter Box to connect the wideband sensor to the XFI ECU. Light gray connector shown is the 7-cavity connector that is attached to the adapter box.

