


Bulkhead connector removed from ECM

Pin C16 (MEM FEED)

Note pin is corroded away



Green and white corrosion due to presence of water in the connector.