
INSTALLATION INSTRUCTIONS

102092 Billet Vacuum Pod - 1984-1985 turbo 3.8L



Note: Gasket is not included. You must fabricate a new gasket in order to install this part.

